Ohio EPA - Daily Discharge Monitoring Report - Form 4500

STATUS:

SUBMISSION ID: FACILITY:

118044

SEDO

American Energy Corp - Century Mine

COUNTY: DISTRICT:

LOCATION:

43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716 Belmont

STATION CODE: MONITORING PERIOD: REPORTING LAB:

PERMIT NUMBER:

Original

01L00091*GD

2010-07-01 To: 2010-07-31 TraDet

William Thompson

ANALYST: NO DISCHARGE INDICATOR:

PARAMETER	Manganese, Total			<u> </u>			
PARAMETER CODE	(Mn) 01055		1	<u> </u>			
UNITS	ug/l	<u> </u>	<u> </u>	<u> </u>			
FREQUENCY	1/2 Weeks						
SAMPLING TYPE	Grab		<u> </u>	<u> </u>			_
2010-07-01	170	ļ		<u> </u>			
2010-07-02				ļ			
2010-07-03		<u> </u>					
2010-07-04		<u></u>					
2010-07-05							
2010-07-06		J		<u> </u>			
2010-07-07							
2010-07-08				<u></u>			
2010-07-09							[
2010-07-10][
2010-07-11							
2010-07-12							
2010-07-13							
2010-07-14							
2010-07-15	1470						
2010-07-16							
2010-07-17							
2010-07-18							
2010-07-19							
2010-07-20							
2010-07-21							
2010-07-22							
2010-07-23							
2010-07-24							
2010-07-25							
2010-07-26							
2010-07-27							
2010-07-28							
2010-07-29							
2010-07-30							
2010-07-31							
Minimum	170.0) (A) (A) (A) (A) (A) (A) (A) (A) (A) (A			
Maximum	1470.0						
Average Count	820		[_
		natural law that I have -	arconally avaminad and	am familiae	Signature of Re	sponsible Official or Author	ized Submission
Name of Responsible Official or Authorized Representative		nalty of law that I have p submitted herein and bas	ed on my inquiry of tho	se		sponsible Official or Author Representative	Date/Time
Cody Mozena	individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment. Page 3						2010-08- 12 14:08